



High Risk Excavation - Raised property retaining wall collapsing into neighbors

- Shows job step by step -



#1 Menai property- retaining wall holding up owners property collapsing onto neighbouring property 3.4 m below



#2 Poorly constructed retaining wall collapsing into neighbors property below. Pic from below



#3 Paint lines drawn by property owners to show movement of rocks in wall structure



#4 Breaking up concrete by hand as edge of retaining wall not stable enough to hold machinery yet



High Risk Excavation - Raised property retaining wall collapsing into neighbors



#5 Shows small space available while starting to carefully dig down with excavator while ensuring wall does not collapse



#6 Need to dig down to neighboring property height 3.4m below so retaining wall can be rebuilt safely to hold weight of owners house and yard above



#7 Only access through owners full garage. Carefully backing through with load of broken concrete and brick



#8 Dirt ramp made from garage entry to deepening excavation. About 2m down now & carefully pulling wall in safely



High Risk Excavation - Raised property retaining wall collapsing into neighbors

- Shows job step by step -



#1 Menai property- retaining wall holding up owners property collapsing onto neighbouring property 3.4 m below



#2 Poorly constructed retaining wall collapsing into neighbors property below. Pic from below



#3 Paint lines drawn by property owners to show movement of rocks in wall structure



#4 Breaking up concrete by hand as edge of retaining wall not stable enough to hold machinery yet



High Risk Excavation - Raised property retaining wall collapsing into neighbors



#5 Shows small space available while starting to carefully dig down with excavator while ensuring wall does not collapse



#6 Need to dig down to neighboring property height 3.4m below so retaining wall can be rebuilt safely to hold weight of owners house and yard above



#7 Only access through owners full garage. Carefully backing through with load of broken concrete and brick



#8 Dirt ramp made from garage entry to deepening excavation. About 2m down now & carefully pulling wall in safely